TENNESSEE DEPARTMENT OF TRANSPORTATION **EROSION PREVENTION/SEDIMENT CONTROL** INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010.

Reason For Inspection:

2nd Weekly

DATE: /2./2.// State Roule (SR) / US Roule or Road Name and Description: Are corrective actions required by this inspection report (Y/N): Wolf River Blvd. County(ies): TDOT PIN: NPDES Permit (NOC) #: Number of New Number of Recurring Number of New Number of Un-Corrected Corrective Actions: Corrective Actions: Shelby Sediment Releases: Sediment Releases: 101615 TNR153299 TDOT Construction No. TDOT Contract No. Contractor: 7994-1535-54 Acuff Enterprises Inc. certify, under penally of law that this document and all attachments were COG EPSC Inspector and Title (print or type): Signature: prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated Gerald "Jerry" Stanfill information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the Contractor EPSC Inspector and Title (print or type): information, I cerify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above I certify that erosion and sediment controls in the drainage area of the Tom Acuff identified outfall where installed as planned and designed in working order as recorded in the table above. I am aware that there are significant penalties for COG EPSC Project Manager submitting false information, including the possibility of fine and impresonment for (print or type): knowing violations Timothy Bierdz TDOT EPSC Inspection Weekly Rainfall Data Log Predicted Rainfall Rainfall Rainfall Rainfall Rainfall Rainfall TDOT/Contractor Agrees with Inspection Report: Dale Day of Week Precipitation Gauge 1 Gauge 2 Gauge 3 Gauge 4 Gauge 5 Gauge 6 Duration NO or YES (%) (in) If No, explain and initial: (in) (in) (in) (in) (in) (hr) 12.11.11 Sunday 0 N/A N/A N/A N/A 12.12.11 Monday FOR COMMENTS. 10 SEE PAGE 2 N/A N/A N/A N/A 12-13-11 Tuesday 20 N/A N/A N/A N/A 12.14.11 Wednesday 20 N/A N/A N/A NIA Thursday 70 N/A N/A N/A N/A 12.9.11 Friday N/A N/A N/A N/A 12/0.11 Salurday

Predicted Precipitation Source:

Sunday

Monday

'www:wealher.com

N/A

Page 1 of /o

(Additional pages may be attached, if needed)

OUTFALL	
AND STA710N	54 corrections has her made
	. So has been deladalot regains.
	. 118/11 Low wet to make conscious at this time. STA 1540 IT corrections will be mode tomosimi
	01 70 600

IE ST	State/US Route o
DITURE	
22 5/15/	

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	12/12/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	11	14+14	LT	12/12/2011		22,35	FM	Weekly cleaning will be required, until further notice.
1A	1	21+50	RT	12/12/2011		41	FM	Const. of RCBC Pedestrian Underpass in progress.
1B	1	22+00	RT	12/12/2011		41	FM	Corrections made to rills and filter socks. See photo
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	w	Monitoring BMP's in place.
2A	1	33+50	LT,CL	12/1/2011	8.7 0.7	12,15,16,24	w	Monitoring BMP's in place.
2B	1	35+50	LT	12/12/2011		16,24	FM	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	FM	Monitoring BMP in place.
4	1	40+00	RT	12/12/2011	T = 10-24-11	15,16,43	СМ	Complete the repair of wash out area along South slope of Lateral C. Note: Contractor was making corrections during inspection. See photo
5A	1	49+00	RT	12/1/2011		16,33	M,RO	Remove sediment in front of silt fences and ditch bottom at two locations. Silt fencing will need to be repaired. See Photos
5B	1	50+00	RT	12/1/2011		9,16,33	FM,W	Monitoring BMP's. Maintenance will be required after job dries out.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch Temporary Mulch Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner Rock Silt Screen FM Future Maintenance **Brush Barrier** C 5 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing Cleaning Needed 6 Sediment Removal 20 **Enhanced Silt Fence** Riprap Outlet Structure Increase Measures Straw Bale Check 7 21 Riprap Energy / Velocity Dissipater Sediment Tube W Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release Berm (soil, riprap, rock) 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 26 CM 12 Temporary Stream Diversion 40 Sheet Pilling Corrections currently being made 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Haul Road Other (O31): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade 14 **Bridge Construction** Other (O#2): Stream Realignment Other (O#3):

CONDITION CODES

State/US	Route o	or Road	Name:

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54

TDOT Contract No.:

Date 12/12/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	12/1/2011		16,24,33	M,RO,W	Temp. Silt fence, Hydro seed, and rip rap installed @ New Channel Realignment. Note Due to rain event. Maintenance is required. Weekly cleaning for stream crossing required. See Photo.
6	1	56+00	LT	12/12/2011			FM	Preparation to drain pond during inspection. Currently Stable.
7	1	60+00	RT	10/24/2011		16, 33	W	Currently Stable, Monitoring BMP's.
8A	1	73+00	RT	12/12/2011		16,24,42	FM,W	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	W	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	12/12/2011	100	16,35,42	W	Bridge construction zone. Monitoring BMP's.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	FM,W	Future maintenance will be required after job site dries out and additional BMP's will be required. See photo
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	W	Monitoring BMP's in place.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	W	Monitoring BMP's in place.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy, Daily M Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 17 3 Temporary Slope Drain **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 6 Riprap Outlet Structure 20 34 Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 22 8 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized Polyethylene Sheeting 25 S 11 Turbidity Barrier / Silt Boom 39 Gabion Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Geotextile 13 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

CONDITION CODES

State/US	Route	or	Road	Name

Wolf River Blvd.

TDOT Construction No.: 79954-3537-54 TDOT Contract No.:

Date	12/12/2011	
() () () () () () () () () ()		_

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM	Corrections made.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM,W	Repairs will be needed after job site dries out.
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM,W	Repairs will be needed after job site dries out.
10C	2	85+50	LT	11/14/2011		15,16,35,41	FM,W	Repairs will be needed after job site dries out.
10D	2	84+50	LT	11/14/2011		15,16,35,41	FM,W	Additional rock needed at RSS (Rock Silt Screen) See photo
11A	2	92+50	RT	11/14/2011		35,41	FM,W	Repairs will be needed after job site dries out.
11B	2	92+50	LT	10/6/2011		10,32,35,41	FM,W	Additional rock needed at RSS (Rock Silt Screen) See photo
11C	2	92+00	LT	10/6/2011		10,32,35,41	FM,W	Additional rock needed at RSS (Rock Silt Screen) See photo
	1	11+28	LT	12/12/2011		19,35	FM	Daily cleaning is required, until further notice
	1	13+40	RT	12/12/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL	12/12/2011	MEASURE CODES	23,29,30	FM	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) U Temporary Slope Drain 17 **Erosion Control Blanket** 3 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 8 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 9 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap Other (O31): 12 26 Temporary Stream Diversion 40 Sheet Pilling Geotextile 13 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

OF THE ST	
ACRICON	
1796 S	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	12/12/2011	

		1	**************************************	[Date of	Cuinting	T	
Outfall Name	Rain	Approx.	LT, RT or	Date Last	Stabilization	Existing EPSC	Current	
or Station No.	Gage	Station No.	Centerline	Disturbed	and Code	Control	Condition	Corrective Action(s) or Comments
(Existing	No.	From / To		2.0.0.00	T = Temp.	Measure	Codes	Constant / Islani(c) or Commonic
Structure)					P = Perm.	Codes*		
'								Daily cleaning will be required, until further
* 109+51	2	East side of WRB	RT	12/12/2011	0.00.00000	19,22	FM	notice.
		South side of						Daily cleaning will be required, until further
* 109+11	2	Farmington	RT	12/12/2011		19,22	FM	notice.
		North side of						Daily cleaning will be required, until further
* 12+80	1	WRB	LT	12/12/2011		19,22	FM	notice.
		Walking Trail						
	1	36+00	LT	7/20/2011	T = 7-20-11	5,35	W	Currently stable, Monitoring BMP's
	4	04- 00-50 01		7/00/0044	T 0 04 44	40	14/	0 11 11
	I	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	W	Currently stable.
		Sta. 13+40 -						Haul roads dampened frequently for dust
		Sta. 107+75	LT, RT or CL	10/13/2011		30	W	control, until further notice.
	0	70.50 400.40	DT	0/00/0044	T = 40 00 44	45.40.05		Maria Burgi
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	FM,W	Monitoring BMP's.
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	FM,W	Monitoring BMP's.
	3.00							Daily cleaning will be required, until further
	1	6+75	LT	12/12/2011		19,22	FM	notice.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	FM,W	Currently stable, Monitoring BMP's
	1	34+00	RT	8/25/2011	T= 8-25-11	16	FM,W	Currently stable, Monitoring BMP's
S=	X. 394.00	EROSIG	ON AND SEDIMEN	T CONTROL ME	ASURE CODES			CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	Ĭ	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	7/2
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

EPSC Inspection

	OF THE ST	
6	TOTAL	
	AGRICULTURE S	
1	1796	

0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

CONDITION CODES


Date _____12/12/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	w	Monitoring BMP's.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	W	Monitoring BMP's.
	11	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	M	Correct wash outs and repair silt fence. See photo.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	w	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	W	Currently stable, monitoring BMP's.
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	W	Currently stable, monitoring BMP's.
* 108+37		North side of WRB	LT	12/12/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	W	Currently stable, monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES


Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 31 Temporary Slope Drain 17 Erosion Control Blanket Ditch Liner Replacement Needed Flexible Channel Liner Rock Check Dams 18 32 Rock Silt Screen Future Maintenance Catch Basin / Storm Inlet Protection Brush Barrier 19 33 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Curb, Gutter, or Storm Sewer Protection Repeat Occurrence Sand Bags 22 36 Sediment Dam RO Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release Temporary Stream Crossing FS 10 Temp Sediment Filter Bag / Dewatering 24 38 Berm (soil, riprap, rock) Final Stabilized Polyethylene Sheeting Turbidity Barrier / Silt Boom 39 S 11 25 Gabion Stable (No Action Needed) Other (O31): 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O#2):_____ 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Sub grade **Bridge Construction** Other (O#3):

EPSC Inspection Page 7 of 10





City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Outfall 5C Sta. 44+00 LT
Maintenance required correcting rills, hydro seed and rip rap. (M,RO,W)



Outfall 8D Sta. 75+50 LT Future maintenance will be required after job site dries out and additional BMP's will be required. (FM, W)




Outfall 10D Sta. 84+50 LT Additional rock needed at RSS (Rock Silt Screen) (FM,W)



Outfall 11B Sta. 92+50 LT and Outfall 11C Sta. 92+00 LT. Additional rock needed at RSS (Rock Silt Screen) (FM. W)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Sta. 25+00 L.T. Correct wash outs and repair silt fence. (M)

No Picture

